

Another PSEG **TIP**

for your Business

Use slow charging battery chargers for forklifts. Many battery chargers will charge a battery in the “fast charge” mode. If your application does not require this, charge the battery over an entire shift (or two shifts) thereby spreading the load and saving energy.

visit: **www.pseg.com**



PSEG

We make things work for you.

